



There is no way to tell by a cursory inspection if these two walls are tied together as would be required in modern construction methods.

Aug 4, 2008 13:07



This photo is another attempt to show the sagging in the roof. This is the south facing slope.

Aug 4, 2008 13:10



This is the old and new construction at its most obvious **Aug 4, 2008 13:16**



The bottom rows of stone show the loss of mortar. The style of placement is not conducive to strength.

Aug 4, 2008 19:16



This view shows more missing mortar which equals a loss of strength. The arrow shows where a couple of stones have bone missing.

Aug 4, 2008 18:17



This is a step crack that is most likely due to the beam pocket.

Aug 4, 2008 13:17