




I saw some open electrical junction boxes in the attic. All junction boxes should have their covers in place to contain sparks should they occur.

Aug 4, 2008 18:31




This flex conduit is not long enough to cover the wire where the sheathing has been stripped off. Aug 4, 2008 13:32




This is the vent (chimney) to the new furnace in the attic. Notice that the required one inch clearance was not provided between the vent and combustibles.

Aug 4, 2008 13:34



This extension cord is being used as permanent wiring which is not within the electrical code. Aug 4, 2008 13:35



This heat supply duct has been taped with a dryer vent. It works but dryer vent is not insulated Aug 4, 2008 13:36



This is a view of a dropped ceiling as seen from the attic **Aug 4, 2008 13:36**