



I saw old knob and tube wiring in the attic but did not determine if it is still in use. All abandon wiring should have been removed when upgrading the electrical system took place.

Aug 4, 2008 13:38



The arrow points to a hole in the original ceiling. The ceilings in use are dropped and there is insulation in those attic spaces. The concern is there are concealed attic spaces that make fighting fire very difficult and dangerous.



A better view into the concealed attic spaces.

Aug 4, 2008 13:40



More knob and tube wiring. This wiring is about the 1930 decade

Aug 4, 2008 13:40



This a general view of the attic. Note the items stored. This is one of the faults with easily accessible attics. Extra loads are placed on the roof system and flammable items could get stored in an attic. (none seen). Note that the attic is poorly ventilated. (no visible light)

Aug 4, 2008 13:41

