


Furnaces in attic receive less maintenance than furnaces that are easily accessible

Aug 4, 2008 13:43



Sorry for the fuzzy picture.

Aug 4, 2008 13:50

This one of the metal posts that has been installed under the roof trusses. These relieve the walls of carrying the full load of the roof.



This is a structural crack at one of the post which is near one on the overhead doors

Aug 4, 2008 13:51